Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/40004CL1035
Work Order Type: Weatherization
Audit Name: 40004CL1035

CLIENT INFORMATION

Client Name: Address:

Client ID: 40004CL1035

Alt. Client ID: MONTGOMERY

<u>AGENCY INFORMATION</u>

Agency: Clarksville-Montgomery CCAA

Agency Phone: (931) 648-5774

Address: (PO Box 487) 350 Pageant Lane, Suite 307

Fax: (931) 648-5784

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1/2 OF DUPLEX - 687 SQ. FT. LOG CABIN BUILT IN 1960 IN A CRAWL SPACE

ALL WORK TO BE DONE IN ACCORDANCE WITH THE TENNESSEE WEATHERIZATION FIELD GUIDE

CONTRACTOR IS RESPLNSIBLE TO VERIFY DIMENSIONS AND SCOPE OF WORK PRIOR TO BID

CERTIFIED FIRM/RENOVATOR REQUIRED

PRE-WORK BLOWER DOOR 3768 @ -50 POST WORK TARGET IS 2250 @-50

AUDIT DATE 3/29/12

Client Name:
Client ID: 40004CL1035
Alt. Client ID: MONTGOMERY

Work Order (Bid Form)
Work Order Name: WO/40004CL1035

DOE Weatherization Assistant Version 8.6.0

Page 1 of 6

Measu	re 1 Infilt	ration Redctn			Componer	ıts			Inspected
Comme	nt 1. SEAL CEILING RIM JOISTS AROUND THE PERIMETER- GAPS OF 1/2 " OR LARGER EXIST - FINISHED PRODUCT MUST PRESERVE THE NATURAL LOOK OF THE CABIN - MAKE IT NEAT AND COLOR IT DARK BROWN								
	2. W/S	WINDOW A/C UNIT							
	REMOVI PROPER 4. AS H	ALL W/S AND DOOR S E EXISTING AND REP R CLOSURE OME TIGHTENS UP, C ATION TARGET	LACE WIT	H NEV	/ - ADJUST	TO INSU			
					Estimated	1		Actual	
# Materia	al / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Misce	llaneous Su	Infiltration Reduction	Each	1					
11		LABOR	Hour						
Other De	etail								
				Measur	e Sub Total:] .	Sub Total:	
Field N	lotes:								

Measure 2 Attic Ins. R-38

Components A1

Comment INSTALL ATTIC ACCESS ENERGY LID- APPROXIMATELY 22" X 22" W/S AND INSULATE

INSTALL DAM AROUND PERIMETER OF MASONARY FIREPLACE

BOX AND SEAL CAN LIGHT

COORDINATE WITH CLIENT TO ALLOW MOVING OWNER ITEMS FOR ACCESS

				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Cellulose, Blown - R-38	SqFt	687					
2 Labor	Attic Insulation - Cellulose, Blown - R-38	SqFt	687					
Other Detail								
			Measur	e Sub Total:]	Sub Total:	
Field Notes:								
Measure 3 Li	ghting Retrofits			Componer	nts 1			Inspected
Comment	gitting itotronits			Componen	21			
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Lighting	Compact Fl 13 Watt	Each Lamp	6					
2 Labor	Compact Fl 13 Watt	Each Lamp	6					
Other Detail								
			Measur	re Sub Total:] .	Sub Total:	
Field Notes:						-		

Client Name: Client ID: 40004CL1035 Alt. Client ID: MONTGOMERY Work Order (Bid Form)
Work Order Name: WO/40004CL1035

Report Run On: 4/2/2012

DOE Weatherization Assistant Version 8.6.0

Page 3 of 6

Measure 4 DW	H Tank Insulation			Componen	ts		ı	nspected
Comment 38 GAL BATHR	LON ELECTRIC WATER OOM	HEATER	IN W	OOD CABIN	ET IN			
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equip	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 5 DW	H Pipe Insulation			Componen				Inspected
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								

	Measure 6 CO	Monitor is Needed			Componen	its		ı	nspected
C	omment INSTALI	NEW CARBON MONC	XIDE DE	ГЕСТС)R				
	Estimated							Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
2	Labor	Labor	Each	1					
C	Other Detail						7		
] []		
				Measur	e Sub Total:]	Sub Total:	
	Comment INSTALI FLOOR	SureRelief Piping Need A PRESSURE RELIEF OR OUTSIDE THE DWI E OF RIGID METAL PIF C PIPE	DISCHAF	RGE PI	SCHARGE	NATE 6" PIPE SH EMPERA	OULD		Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Health and Safety	-	Each	4 <i>ty</i>	Omit Cost	TOtal	Qiy	Onit Cost	Total
	Labor	Labor	Each	1					
		24201		-					
	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

	Measure 8 Smo	ke Detector is Needed			Componen	ts			Inspected
C	omment INSTALL	NEW SMOKE DETECT	TOR- IN F	IALLW	AY NEAR B	EDROO	MS		
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke detector	Each	1					
2	Labor	Labor	Each	1					
(Other Detail						,		
L									
				Measur	e Sub Total:] .	Sub Total:	
	Field Notes:								
L		[
			Work Or	der Gra	nd Total:		Gran	d Total:	